

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2021

Submitted Date:

05/14/2021

Document Number:

701101492

**FIELD INSPECTION FORM**Loc ID 335408 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Kellerby, Shaun       |              | shaun.kellerby@state.co.us         |         |
| Inspection, Terra TEP | 970-285-9377 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 257640      | WELL | PR     | 12/31/2005  | OW         | 045-07419 | UNOCAL GM 11-34    | PR          |
| 262448      | WELL | PR     | 09/17/2003  | GW         | 045-08028 | WILLIAMS GM 224-34 | PR          |

**General Comment:**

COGCC Follow Up Inspection Report Summary  
Follow up to 1/13/2021 inspection # 701101020  
Corrected action item(s)  
Cattle guard at main road entrance is not intended for a storm water BMP.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Emergency Contact Number:**

|                    |     |             |
|--------------------|-----|-------------|
| Comment:           | 911 |             |
| Corrective Action: |     | Date: _____ |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                    |  |       |                 |
|--------------------|--|-------|-----------------|
| Type: Bradenhead   | # 2                                    |       | corrective date |
| Comment:           | Braden head accessible for monitoring. |       |                 |
| Corrective Action: |  | Date: |                 |
| Type: Plunger Lift | # 2                                    |       |                 |
| Comment:           |  |       |                 |
| Corrective Action: |  | Date: |                 |

**Tanks and Berms:**

| Contents           | #                               | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------------------------------|----------|------|---------|--------|
|                    |                                 |          |      |         |        |
| Comment:           | Remote shared facility # 335306 |          |      |         |        |
| Corrective Action: |                                 |          |      |         | Date:  |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 257640 Type: WELL API Number: 045-07419 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 262448 Type: WELL API Number: 045-08028 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Compaction              |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
| Seeding          |                 |                         |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
| Check Dams       |                 |                         |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
|                  |                 | Culverts                |                       |               |                          |         |
| Ditches          |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 701101493    | Inspection 701101492 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429907">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429907</a> |