

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402690450

Date Received:  
05/16/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699103336

Inspection Date: 04/05/2021

FIR Submit Date: 04/05/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 445300

Location Name: Cockroft Number: 5N63W19C County: \_\_\_\_\_

Qtrqr: SENE Sec: 19 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.388060 Longitude: -104.474180

FACILITY - API Number: 05-123-00 Facility ID: 445300

Facility Name: Cockroft Number: 5N63W19C

Qtrqr: SENE Sec: 19 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.388060 Longitude: -104.474180

CORRECTIVE ACTIONS:

1 CA# 148091

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 04/26/2021

Response: CA COMPLETED

Date of Completion: 04/07/2021

Operator Comment: Stained soil has been removed and treated, valve was slightly open and has been shut and is no longer leaking, and the trash has been removed from location. Satisfactory Follow-Up Inspection #699103556 done. CA's complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 148092

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 04/26/2021

Response: CA COMPLETED

Date of Completion: 04/07/2021

Operator Comment: Stained soil has been removed and treated, valve was slightly open and has been shut and is no longer leaking, and the trash has been removed from location. Satisfactory Follow-Up Inspection #699103556 done. CA's complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 148093

Corrective Action: Comply with Rule 606

Date: 04/26/2021

Response: CA COMPLETED

Date of Completion: 04/07/2021

Operator Comment: Stained soil has been removed and treated, valve was slightly open and has been shut and is no longer leaking, and the trash has been removed from location. Satisfactory Follow-Up Inspection #699103556 done. CA's complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Stained soil has been removed and treated, valve was slightly open and has been shut and is no longer leaking, and the trash has been removed from location. Satisfactory Follow-Up Inspection #699103556 done. CA's complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: \_\_\_\_\_

Title: EHS Coordinator

Date: 5/16/2021 4:33:05 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

| Document Number | Description |
|-----------------|-------------|
|                 |             |

Total Attach: 0 Files