

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #3812 from entrance to location.



Photo #3370 from inspection #699802865 conducted on 4/5/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #3813 location lacks stabilization.



Photo #3371 from inspection #699802865 conducted on 4/5/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #3814 Location lacks stabilization.



Photo #3372 from inspection #699802865 conducted on 4/5/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #3815 No form of tracking BMP located at the entrance to location.



Photo #3374 from inspection #699802865 conducted on 4/5/21.