



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Bradenhead	# 1				
Comment:	Appears to be plumbed to surface.				
Corrective Action:		Date:			
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:		Date:			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 248031 Type: WELL API Number: 123-15829 Status: SI Insp. Status: SI**Idle Well**Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 07/24/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">COGCC Inspection Report Summary</a> On Monday 5/17/21 at approximately 1249hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Spike ST GWS 30-14 of Noble Energy Location ID: 328307 in Weld County, Colorado. While there, I observed a well that is SI. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.	burnsa	05/17/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699103663	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5431216">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5431216</a>