



Lorencito 14-20-34-66

Cleaned up area of impacted soil under drive head also repaired source of leak for hydraulic oil. To comply with 901.b in handling solid waste material. Also complied with Rule 608.e. inspection and repair of leaks at regular intervals