

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2021

Submitted Date:

05/18/2021

Document Number:

690201545

**FIELD INSPECTION FORM**Loc ID 307278 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		batwater@ogrisop.com	
Arthur, Denise		denise.arthur@state.co.us	
		efitzgerald@ogrisop.com	
		rmack@ogrisop.com	
		timothy.thomsen@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217352	WELL	PR	09/12/2012	GW	071-06128	APACHE CANYON 12-14	RI

**General Comment:**

This is a follow up of the previous stormwater management inspections; #690200600, #690200709, #690200848, #690201265.  
The corrective action of the previous inspections have not been performed.  
Non-compliance with the Rules will be considered for enforcement.  
See attached photos and additional details within this report.

Operator is directed to perform corrective actions outlined on this inspection report immediately. This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 523.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Fail			
		Culverts	Fail			

Comment: There are culverts along the main road in the canyon that need to be repaired and maintained. Additional BMP's are needed along the steep grade of the road side. There is vehicle rutting occurring on the road ascending to the location. The road needs to be maintained to prevent erosion. Areas of erosion along the road needs to be repaired and properly stabilized. Previous corrective action has not been completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/18/2020

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	258528	881802	
	258528	881802	

**COGCC Comments**

Comment	User	Date
Further stormwater erosion will occur with seasonal high intensity storm events if BMP's are not properly monitored and maintained. BMP's must be installed and maintained for all seasonal storm events to prevent erosion.	CostaR	05/18/2021
Refer to photos for additional issues observed.	CostaR	05/18/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690201546	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5432157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5432157</a>