

Inspection Photos

Operator: Bayless

Date: 5/11/2021



Photo 1. View of the reclaimed access road from the access entrance facing west, toward the reclaimed well pad.



Photo 2. View of the reclaimed well pad from the northwestern corner facing center.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of surface pipeline and associated equipment remains in place.



Photo 5. View of cable debris west of the reclaimed well pad.



Photo 6. View of the reference area comprised of mixed james galleta grassland and wolfberry shrubland with a diversity of shrubs and herbs such as shadscale, purple threeawn, Indian paintbrush, and goldenaster.