

Inspection Photos  
Operator: Simcoe  
API: 067-09079  
Date: 5/17/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with a mixture of grasses such as western wheatgrass, smooth brome, and sand dropseed.



Photo 3. View of southern project area from the southeastern corner facing westward.



Photo 4. View of the reference area comprised of ponderosa pine forest with understory of gambel oak, Oregon grape, *Poa secunda*, and serviceberry.