

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2021

Submitted Date:

05/12/2021

Document Number:

697003682

FIELD INSPECTION FORMLoc ID 319247 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10454

Name of Operator: PETROSHARE CORPORATION

Address: 9635 MAROON CIRCLE #400

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		fwitsell@petrosharecorp.com	
Kraich, Adam		adam.kraich@state.co.us	
,		dnr_cogccengineering@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243144	WELL	PR	10/01/2018	GW	123-10935	RMPCO KISSLER 1	SI

General Comment:

Production and Bradenhead reports appear to be delinquent, please contact COGCC engineering.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced water vault lacks capacity placard. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/13/2021

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Calibration card is current		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	Clean out plate is leaking. See attached photo.				
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.				Date: 08/13/2021

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Secondary containment is inadequate to contain 150% of the volume of the largest tank. See attached photo of the north berm wall.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 08/13/2021

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:	Unknown capacity. Produced water vault has uncovered openings on top of vault. Wildlife protections devices not adequate. See attached photo.				
Corrective Action:	Install or repair wildlife protection equipment per Rule 902.b.				Date: 08/13/2021

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
--------	----

Inspector Name: Peterson, Tom

Comment:		
Corrective Action:		Date:
Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 243144 Type: WELL API Number: 123-10935 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 01/07/2020Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 20

Fluid Type: _____

End Surf Csg Pressure: 20

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 5/12/2021 at approximately 08:45 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Petroshare RMPCO Kissler 1 location #319247 in Weld County, Colorado.</p> <p>While there, I observed that the crude oil tank berm was insufficient, the produced water vault lacked capacity placards, the crude oil tank clean out plate was leaking and the produced water vault had uncovered openings. During this inspection the following possible compliance issues were observed: Rule 603.o.with a corrective action date of 8/13/2021. Rule 605.h.with a corrective action date of 8/13/2021, Rule 608.e.with a corrective action date of 8/13/2021, Rule 902.b.with a corrective action date of 8/13/2021.</p> <p>.A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	05/12/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402687399	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5427369
697003683	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5427360