

Inspection Photos

5/14/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 452807

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 1: Photo taken from the south end of the Location, facing northwest. Photos 1-3 provide an overview of the Location from northwest, north to northeast. Photos also show that interim reclamation of areas not needed for production on the Location has not been conducted in accordance with 1003 Rules and Corrective actions.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 4: Photo taken from the south end of the Location, facing west. See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 5 Photo taken from the west end of the Location, facing north. Photo shows Operator has maintained perimeter control measures to manage stormwater runoff from the Location. Photo also shows that required control measures to protect/stabilize the fill slopes on the Location remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 6: Photo taken from the west end of the Location, facing southwest. Photo shows Operator has maintained perimeter control measures to manage stormwater runoff from the Location. Photo also shows that required control measures to protect/stabilize the fill slopes on the Location remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 7: Photo taken from the east end of the Location, facing south. Photo shows that required control measures to protect/stabilize the fill slopes on the Location remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 8: Photo taken from the access road, facing south. Previous inspection required Operator to conduct additional reclamation along the access road, and to implement control measures to stabilize the seeded soils; unable to find evidence that additional reclamation was performed, and control measures installed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 9: Photo taken from the access road, facing north. Previous inspection required Operator to conduct additional reclamation along the access road, and to implement control measures to stabilize the seeded soils; unable to find evidence that additional reclamation was performed, and control measures installed.