

Inspection Photos

5/14/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 335647

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335647



Photo 1: Photo taken from doc. #696202107. 2019 COGIS Aerial imagery. Photo shows two access points/roads have been constructed on the south end of the Location (dotted yellow lines). Previous inspection required reclamation of areas not needed for production on the south end of the Location, and the western traveling access road (arrow) also on the south end of the Location; It was observed that reclamation has not been conducted.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335647



Photo 2: Photo taken from doc. #696202107. Google Earth aerial imagery. Photo shows areas of the Location not needed for production operations have not been reclaimed. Red circles represent a 75 foot buffer around producing wells.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 4: Photo taken from the southwest end of the Location, facing north. Photos 4-6 provide an overview of the Location from north, northeast to southeast. Photos also show that interim reclamation of areas not needed for production on the Location has not been conducted in accordance with 1003 Rules and Corrective actions.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 5 See comments under photo 4.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 6: See comments under photo 4.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 7: Photo taken from the south end of the Location, facing northwest. Photos 7-9 provide an overview of the Location from northwest, northeast to east. Photos also show that interim reclamation of areas not needed for production on the Location has not been conducted in accordance with 1003 Rules and Corrective actions.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



20210514

Photo 8: See comments under photo 7.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 9: See comments under photo 7. Previous inspection documented that two access points/roads have been constructed on the south end of the Location; inspection required Operator to reclaim areas on the south end of the Location, including the southern access road/point. Photo also shows access road on the south end of the Location has not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 10: Photo taken from the main lease road, facing west. Photos 10-11 show that two access roads/points have been constructed on the Location. Photo also shows access road on the south end of the Location has not been reclaimed.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 11: Continued from photo 10. Photo shows the second access road/point to the Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 12: Photo taken from the cut slopes, facing northwest. Previous inspection required Operator to install temporary control measures on slopes until interim reclamation is conducted. Photo shows hydromulch has been applied to slopes; BMP is inadequate for long term stabilization and is showing signs of degradation.

