

Inspection Photos

5/14/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 335902

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north. Photos also show that interim reclamation of areas not needed for production have been conducted.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 5: Photo taken from the interim areas on the northeast end of the Location, facing north. Previous inspection required Operator to implement control measures to stabilize the seeded soils. Photo shows that control measures to stabilize the slopes and soils of the interim areas of the Location have not been implemented or maintained.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 6: Photo taken from the interim areas on the northeast end of the Location. Photo shows erosion degradation observed on interim areas. Previous inspection required Operator to implement control measures to stabilize the seeded soils; control measures to stabilize the slopes and soils of the interim areas of the Location have not been implemented or maintained.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 7: Photo taken from the interim areas on the north end of the Location, facing west. Previous inspection required Operator to implement control measures to stabilize the seeded soils. Photo shows that control measures to stabilize the slopes and soils of the interim areas of the Location have not been implemented or maintained.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 8: Continued from photo 7. Photo shows erosion degradation (rilling) observed on interim areas. Previous inspection required Operator to implement control measures to stabilize the seeded soils; control measures to stabilize the slopes and soils of the interim areas of the Location have not been implemented or maintained.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 9: See comments under photo 8. Photo shows stormwater erosion degradation (rilling) observed on interim areas.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 10: Photo taken from the former cut slope on the west end of the Location, facing northeast. Surface roughening (tracking) observed on western slopes of the Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 11: Photo taken from the former cut slope on the west end of the Location, facing southeast. Surface roughening (tracking) observed on western slopes of the Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335902



Photo 12: Photo taken from the fill slopes on the southeast end of the Location. Photo shows BMPs to protect/stabilize the fill slopes of the Location remain missing or insufficient.

