

# Inspection Photos

5/14/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324375

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324375



**Photo 1:** Photo taken from the south end of the Location, facing west. Photos 1-3 provide an overview of the Location from west, north to east. Operator appears to have conducted final reclamation activities on the well site, however very little desirable vegetative germination was observed.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324375



**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324375



**Photo 3:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 324375



**Photo 4:** Photo taken from the Location entrance, on the south end of the site. Photo shows plastic pipe with wires observed within. Equipment requires removal.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324375



**Photo 5:** Photo taken from the northwest end of the Location, facing northwest. Photo shows control measures to stabilize the soils and manage stormwater runoff is missing or insufficient; erosion degradation evident.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324375



20210514

**Photo 6:** Photo taken from the northwest end of the Location, facing northwest. Photo shows control measures to stabilize the soils and manage stormwater runoff is missing or insufficient; erosion degradation evident. .



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 324375



**Photo 7:** Photo taken from the access road, south of the Location, facing south. Photo shows erosion degradation due to stormwater runoff on the access road; arrow shows sediment deposition on and off the road. Stormwater BMPs missing or insufficient on the access road. Photo also shows access road has not been reclaimed in accordance with 1004 Rules.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 324375



**Photo 8:** Continued from photo 7. Photo shows erosion degradation and sediment deposition occurring at the access road.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 324375



**Photo 9:** See comments under photo 7,



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324375



**Photo 10:** Photo taken from the former cut slope on the west end of the Location, facing northeast. Surface roughening (tracking) observed on western slopes of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 324375



**Photo 11:** Photo taken from the access road, facing northwest. Photo shows access road has not been reclaimed in accordance with 1004 Rules; Access road requires, at a minimum, compaction alleviation, recontouring/regrading and revegetation activities.

