

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2021

Submitted Date:

05/13/2021

Document Number:

700300135

FIELD INSPECTION FORMLoc ID 325310 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 31250

Name of Operator: FRITZ & DIGMAN INC

Address: PO BOX 70024

City: ALBUQUERQUE State: NM Zip: 87197-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Fields, Vanessa		vanessa@walsheng.net	
Andrews, Vern		vern@walsheng.net	
Digman, Bernie	575-640-1867	berniekdigman@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214538	WELL	PR	08/01/2020	OW	067-06141	DAKOTA FEE 1	PR

General Comment:

Also see 5/5/21 reclamation inspection Doc#693903152

Location			
Lease Road:			
Type			
comment:	see 5/5/21 reclamation inspection		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	oily non servicable parts/valve stored inside pumpjack frame (see photo)		
Corrective Action:	remove non-servicable parts/parts not necessary for ongoing operations		Date: 06/01/2021
Type	OTHER		
Comment:	stuffing box leak reapiored and free oil no longer present, some impacted material removed, some discolored saturated soil with odor still remains/observed with shovel test. Note" valve on end of vertical riser near wellhead with slight leak of crude oil		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Operator emailed scanned Form 17 but has yet to upload them electronically. Note: monthly pressure monitroing and record keeping is also required per Rule 419		
Corrective Action:		Date:	
Venting:			

Yes/No	YES		
Comment:	casing gas running through above ground flowline to flare device. Form 4 approved for vent/flare in 2019		
Corrective Action:		Date:	

Flaring:

Type	Other	
Comment:	converted fire tube burning gas	
Corrective Action:	Submit new sundry notice for vent/flare/combust per Rule 903.d(3)	Date: <u>06/01/2021</u>

Optical Gas Imaging Survey

Survey Type: _____

Current Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: _____ Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F) _____

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHEComment: correctiue action regarding tank seals from FIR doc# 700300118 satisfactorily performedCorrective Action: Date: _____**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402688456	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428314
700300145	bradenhead access, wellhead area, shovel test	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428303
700300146	weeping valve	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428304
700300147	unused/non-servicable equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428305
700300148	oily rag	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428306
700300149	crude oil streak down side of tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428307