

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2021

Submitted Date:

05/13/2021

Document Number:

700300138**FIELD INSPECTION FORM**Loc ID 325092 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31250Name of Operator: FRITZ & DIGMAN INCAddress: PO BOX 70024City: ALBUQUERQUE State: NM Zip: 87197-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fields, Vanessa		vanessa@walsheng.net	
Digman, Bernie	575-640-1867	berniekdigman@gmail.com	
Andrews, Vern		vern@walsheng.net	

General Comment:[Also see 5/5/21 reclamation inspection Doc#693903150](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	impacted material removed, gearbox not leaking at time of inspection, corrective action from FIR doc#700300127 satisfactorily performed		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	lube oil container cited in previous inspection 700300127 stored without adequate spill prevention is still stored without spill prevention (pumpjack frame is not adequate, bare ground, daylight beneath beams)		
Corrective Action:	remove or store with adequate spill prevention if necessary for ongoing operations	Date:	04/19/2021
Type	UNUSED EQUIPMENT		
Comment:	flowline and flare device not in use		
Corrective Action:	use or remove unused equipment or explain why it is necessary to remain on site for ongoing operations per Rule 606	Date:	06/14/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: impacted material removed, corrective action from FIR doc#700300127 completed (note: still some discolored soil observed after shovel test)

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:		corrective date
Type: Bradenhead	# 1	

Comment:	Operator emailed Form 17 from bradenhead test but has not filed them electronically. Note: monthly monitoring and record keeping is required by Rule 419		
Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:	well producing with casing valve in closed position at time of inspection, no approved sundry for vent/flare, flowline and converted fire tube on site not in use at time of inspection.		
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
		Compaction	Pass			

Comment: plastic lube oil container stored inside pumpjack frame with no spill prevention, see housekeeping section

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start AM/PM Time Survey End AM/PM

Equipment

Wellhead(s)

Oil Tank(s)

Comment: tank appears to be operating as ventless

Corrective

Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402688457	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428315
700300150	unused equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428308
700300151	impacted are cleaned up	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428309
700300152	wellhead/bradenhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428310
700300153	shovel test	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428311