

Inspection Photos
Operator: XTO
API: 067-07683
Date: 5/17/2021



Photo 1. View of project area from southwestern corner facing center.



Photo 2. View of tanks and equipment needs to be removed.



Photo 3. View of access road needs to be reclaimed. Black bag and trash need to be removed. Open site is providing access for trash dumping.



Photo 4. View of the western cut slope facing southward from the southwestern corner.



Photo 5. View of dense musk thistles and Canada thistles observed within the project area. Approximately 1000 Canada thistles and 500 musk thistles observed.



Photo 6. View of cut-slope within the southwestern project area, approximately 30 feet high. Bare soils and little vegetation observed on slope needing recontouring, slope reduction, and stabilization.



Photo 7. View of the reference area comprised of ponderosa pine woodland with understory of gambel oak, western wheatgrass, muttongrass, serviceberry, and mountain mahogany