

Inspection Photos
Operator: Hilcorp
API: 067-07814
Date: 5/17/2021



Photo 1. View of project area from northwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass, smooth brome, and goldenaster.



Photo 3. View of erosional downcutting at the top of the eastern cut slope facing. Exposed roots demonstrate lack of stabilization at the top of the cut-slope.



Photo 4. View of the reference area comprised of ponderosa pine woodland with understory of gambel oak, western wheatgrass, muttongrass, serviceberry, and mountain mahogany