

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/18/2021

Submitted Date:

05/20/2021

Document Number:

701500818

**FIELD INSPECTION FORM**
 Loc ID 399062 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 8220

Name of Operator: BIASI\* BRUNO

Address: P O BOX 60

City: BUNKERVILLE State: NV Zip: 89007

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261676	WELL	PA	07/01/1988	OW	103-40370	WOOSLEY 2	PA

**General Comment:**

A follow up inspection of FIR documents:

- 1) 662300283 dated 3-9-2012
- 2) 675100556 dated 10-21-2014
- 3) 674300113 dated 10-28-2014
- 4) 608101996 dated 6-17-2017

The following compliance issues are uncompleted:

- 1) Spilled oil from tanks
- 2) Unused equipment - tanks, pump jack & deadman
- 3) Various steel trash

Note: Last well used by tank battery plugged in 1998. Location on BLM land.

40.073566, -108.781343 Database coordinate

40.07364, -108.78164 Actual coordinate

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well marker with lettering "BRUNO BIASI WOOSLEY #2" & "C-04180-A"		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Cables, steel parts, concrete pad.		
Corrective Action:	Comply with Rule 606.		Date: 11/28/2014
Type	UNUSED EQUIPMENT		
Comment:	2 tanks, pump jack & deadman.		
Corrective Action:	Comply with Rule 606.		Date: 11/28/2014

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Crude Oil	Tank	>= 5 bbls		
Comment:	Spilled oil from 2 tanks that was first recorded in the 2012 inspection. The spill size of the upper tank increased from the 2014 to 2017 inspection, then has remained the same. The lower tank appears to have leaked slightly since the 2017 inspection. Both tanks sounded empty or near empty.			
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.			Date: 11/07/2014

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 261676 Type: WELL API Number: 103-40370 Status: PA Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: PA in 1988.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						Vegetation.

Comment:

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500819	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5437856">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5437856</a>