

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2021

Submitted Date:

05/21/2021

Document Number:

700600266

**FIELD INSPECTION FORM**

Loc ID: 309284  
Inspector Name: Kosola, Jason  
On-Site Inspection:   
2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments  
 0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 10705  
 Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
 Address: 1875 LAWRENCE ST STE 1150  
 City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Duran, Alicia		alicia.duran@state.co.us	
Burger, Craig		craig.burger@state.co.us	
Inspections, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Beardslee, Tom		tom.beardslee@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291012	WELL	PR	08/09/2007	GW	071-09336	STOOPS 12-1	EI

**General Comment:**

This is an environmental inspection to document use of open top tank during hydraulic fracturing process and COGCC Rule 903.c compliance. See attached photos.

Fluid flowing uphole is sent to open top tank on an intermittent basis several minutes at a time during the fracking process. Fluid flows through pipe in open tank (shown in photos) and then flows into open top tank. Fluid flowing through pipe is agitated and it is likely that any gas in solution is off gassed during this process. Cumulative "venting" from open top tank would likely be less than 24 hours.

Inspector recommended that operator keep a time log of fluid flowing into tank as well as develop a system to obtain a gas sample from from tank to define composition of any gas vented.

COGCC will discuss process internally and provide recommendation to operator.

**Inspected Facilities**

Facility ID: 291012 Type: WELL API Number: 071-09336 Status: PR Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700600267	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5437941">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5437941</a>