

Inspection Photos  
Operator: Simcoe  
API: 067-07860  
Date: 5/19/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, smooth brome, willows, and rubber rabbitbrush.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of the reference area comprised of sagebrush shrubland and irrigated grassland mosaic with big sagebrush, western wheatgrass, smooth brome, and scattered juniper trees observed.



Photo 5. View of closed gate at entrance to access road after leaving location.