

Inspection Photos  
Operator: Simcoe  
API: 067-06339  
Date: 5/19/2021



Photo 1. View of project area from well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing outside of fenced working area with grazed grasses and sedges largely in a grazed and early season vegetative condition similar to surrounding reference area vegetation.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 5. View of closed gates at after leaving location.