

Inspection Photos
Operator: Simcoe
API: 067-09822
Date: 5/19/2021



Photo 1. View of project area from well pad northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is sparse and weedy within the majority of the northern project area. Spot seeding is needed.



Photo 3. View of Canada thistles (approx. 200) and Russian knapweeds (approx. 300) observed within the project area.



Photo 4. View of the reference area comprised of irrigated grass field with grasses such as western wheatgrass and smooth brome.