

# Inspection Photos

5/21/2021

Operator: GUNNISON ENERGY LLC # 10515

Location ID: 453805

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

**Inspection Photos**  
**Operator Name: GUNNISON ENERGY LLC # 10515**  
**Location ID: 453805**



**Photo 1:** Photo taken from the Location entrance, facing northwest. Photo shows signage.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 453805



**Photo 2:** Photo taken from the east end of the Location, facing southeast. Photo shows Location entrance. Though off-site sediment transport concerns were not observed, photo shows that control measures to prevent vehicle sediment tracking are missing. Advise implementing control measures to mitigate/minimize off-site sediment transport prior to tracking issues.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 453805



**Photo 3:** Photo shows silt fence constructed along the southern and western perimeters of the Location.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 453805



**Photo 4:** Photo shows silt fence constructed along the southern and western perimeters of the Location.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 453805



**Photo 5:** Photo taken from the topsoil stockpile on the north end of the Location. Photo shows stormwater BMPs at the soil stockpile to prevent offsite sediment transport are missing or insufficient.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 453805



**Photo 6:** Photo taken from the topsoil stockpile on the north end of the Location. Photo shows stormwater BMPs at the soil stockpile to prevent offsite sediment transport are missing or insufficient.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 453805



**Photo 7:** Photo taken from the north end of the Location, facing southeast. Photo shows location construction, and soil salvage/segregation activities in process.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 453805



**Photo 8:** Photo shows musk thistle remnant from the 2020 growing season. Due to the disturbance activities from construction, noxious weeds on the location may become an ongoing issue without vigilant monitoring and management.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 453805



**Photo 9:** Photo of the cut slope on the east end of the cut slope. Photo shows surface roughening to stabilize soils on the slope.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 453805



20210521

**Photo 10:** Photo taken from the newly constructed access road south of the Location, facing northeast. Photo shows stormwater and erosion control measures along the access road are missing or insufficient.

Inspection Photos  
Operator Name: GUNNISON ENERGY LLC # 10515  
Location ID: 453805



**Photo 11:** Photo taken from the newly constructed access road east of the Location, facing southwest. Photo shows stormwater and erosion control measures along the access road are missing or insufficient.