

TEP
Miller 5
Location # 417475



location



location

TEP
Miller 5
Location # 417475



location



Debris

TEP
Miller 5
Location # 417475



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
Miller 5
Location # 417475



Lack of stabilization/compaction looking north into pad



Lack of stabilization/compaction looking South/west leaving pad