

Inspection Photos

API: 071-08840

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/24/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021

Inspection Photos



Photo 1. It was observed that branches and logs are being piled along the side of the road. It is a concern that braches and logs will obstruct stormwater flow and direct stormwater onto the road.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021

Inspection Photos



Photo 2. Facing west along the main access road. There are areas along the road that have vehicle rutting and erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021

Inspection Photos



Photo 3. This culvert is partially filled in with sediment at Lat/Long:37.2112, - 104.9298.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021

Inspection Photos



Photo 4. Stormwater is not properly directed toward the culvert and there is gravel obstructing the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021

Inspection Photos



Photo 5. There is an erosion channel along the side of the road. Arrow points to 4.5 ft. shovel to show depth of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021

Inspection Photos



Photo 6. BMP's need to be installed along the side of the road to prevent erosion at this area, Lat/Long:37.20905,-104.9369.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021

Inspection Photos



Photo 7. Facing west along the main access road. There are areas along the road that have vehicle rutting and erosion. The road needs to be maintained and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021

Inspection Photos



Photo 8. There is vehicle rutting where trucks are backing into the receiver/launcher.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021

Inspection Photos



Photo 9. Facing northeast toward the location. Vegetation is established in the interim area and the location is stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021

Inspection Photos



Photo 10. Facing north toward the location. Vegetation is established in the interim area and the location is stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08840 | Date: 5/24/2021