

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2021

Submitted Date:

05/24/2021

Document Number:

699803138

**FIELD INSPECTION FORM**Loc ID 334317 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268622	WELL	PR	09/01/2020	GW	045-09277	BATTLEMENT MESA 27-44	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 5/24/21 at approximately 14:00 hours, I, Inspector Corey De Paolo,  
Conducted an on-site inspection at CAERUS PICEANCE LLC BATTLEMENT MESA-67S95W /27SESE,  
Location #334317 in Garfield County Colorado.  
While there, I observed normal production operations.  
During this inspection the following compliance issues were observed:

1) Location lacks stabilization. No form of tracking BMP at entrance to location with a corrective action date of 6/8/21.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		

Comment:		Date:	
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift	Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	All meter runs have been calibrated in the last year.	Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gallon
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Separate containment			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Separate containment			
Corrective Action:	Date:			



Inspected Facilities									
Facility ID:	268622	Type:	WELL	API Number:	045-09277	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Berms				
Check Dams						
Ditches						
		Gravel				
Other	Fail					
		Ditches				
Sediment Traps						
Compaction	Fail					
		Check Dams				
Gravel	Fail					
Berms						
		Sediment Traps				
Rip Rap						

Comment: [Location lacks stabilization. No form of tracking BMP at entrance to location.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 06/08/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Storm water for corrective actions.</a>	depaoloc	05/24/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803139	Photos for Insp. #699803138	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440000">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440000</a>