

Inspection Photos

5/21/2021

Operator: SG INTERESTS I LTD - 77330

Location ID: 414132

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 1: Photo taken from the southeast end of the Location, facing west. Photos 1-3 provide an overview of the Location from west, northwest to north. Photos show reclamation of unused areas not needed for production has not been performed in accordance with 1003 Rules.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 4: Photo taken from the southeast corner of the Location. Previous inspections observed that the Slope drone has not been maintained in proper functioning condition; inlet filled with sediment. Photo shows inlet of the slope drain remains filled with sediment.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 5: Photo taken from the southeast corner of the Location. Photo shows slope drain. Previous inspections documented that the slope drain was not constructed with an appropriate outlet per good engineering practices. Photo shows slope drain has not been constructed with an appropriate outlet.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 6: Photo taken from the southwest corner of the Location. Photo shows slope drain. Previous inspections documented that the slope drain has not been constructed with an appropriate outlet per good engineering practices. Photo shows slope drain remains improperly constructed with an appropriate outlet per good engineering practices.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 7: Continued from photo 6. Photo shows slope drain has not constructed with an appropriate outlet per good engineering practices.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 8: Photo taken from the southwest corner of the Location. Photo shows sediment trap. Precious inspections documented that the sediment trap has not been constructed with an appropriate outlet per good engineering practices. Photo shows outlet has not been not constructed in accordance with good engineering practices; outlet missing geotextile lining; scouring/degradation becoming evident around riprap at outlet. Trap also does not appear to be appropriate in size.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 9: See comments under photo 8. Photo shows outlet missing geotextile lining per good engineering practices; scouring/degradation becoming evident around riprap at outlet



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 10: Photo taken from the slopes on the west end of the Location. Previous inspections documented that control measures to protect/stabilize slopes on the Location were missing or insufficient. Photo shows control measures to protect/stabilize slopes on the Location remain missing or insufficient.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 11: See comments under photo 10.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 12: Photo shows noxious weed rosette observed on the western slopes of the Location.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 13: Photo taken from the topsoil stockpile on the west end of the Location. Previous inspections documented that control measures to protect/stabilize slopes on the Location were missing or insufficient. Photo shows control measures to protect/stabilize slopes on the Location remain missing or insufficient.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 14: See comments under photo 13.



Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 414132



Photo 15: Photo shows noxious weed rosette observed on the berm along the northwest end of the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 16: Photo taken from the north end of the Location. Previous inspections documented that control measures to protect/stabilize slopes on the Location were missing or insufficient. Photo shows control measures to protect/stabilize slopes on the Location remain missing or insufficient.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 17: See comments under photo 16.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 414132



Photo 18: See comments under photo 16

