

# Inspection Photos

5/21/2021

Operator: SG INTERESTS I LTD - 77330

Location ID: 418697

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 1:** Photo taken from the east end of the Location, facing east. Photo shows section of the Location's perimeter stormwater diversion ditch armored with geotextile lining and rip-rap.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 2:** Photo taken from the east end of the Location, facing north. Photo shows the 2<sup>nd</sup> stormwater diversion ditch around perimeter of the pad.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 3:** Photo taken from the east end of the Location, facing north. Photo shows the perimeter stormwater diversion ditch. Photo also shows control measures to protect/stabilize slopes and disturbed areas of the Location remain missing or insufficient. Unable to find evidence that revegetation activities were performed, and BMPs to stabilize seeded soils implemented. Erosion degradation evident.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 4:** Photo taken from the northeast corner of the Location, facing southwest. Photo shows perimeter stormwater diversion ditch installed on Location is inadequate/insufficient for the site's conditions; diversion ditch not in proper functioning condition.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 5:** Continued from photo 4. Photo shows perimeter stormwater diversion ditch installed on Location is inadequate/insufficient for the site's conditions; ditch not in proper functioning condition. Photo also shows control measures to protect/stabilize slopes of the Location remain missing or insufficient.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 6:** Continued from photo 5. Photo shows cut slopes on the Northeast end of the Location. Photo shows runoff causing erosion degradation on the slopes. Control measures to protect/stabilize slopes and disturbed areas of the Location remain missing or insufficient. Unable to find evidence that revegetation activities were performed, and BMPs to stabilize seeded soils implemented.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 7:** Photo taken from the north end of the Location, facing north. Photo shows control measures to protect/stabilize slopes and disturbed areas of the Location remain missing or insufficient. Unable to find evidence that revegetation activities were performed, and BMPs to stabilize seeded soils implemented.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 8:** Photo taken from the north end of the Location, facing west. Photo shows control measures to protect/stabilize slopes and disturbed areas of the Location remain missing or insufficient. Unable to find evidence that revegetation activities were performed, and BMPs to stabilize seeded soils implemented.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 9:** Photo taken from the north end of the Location, facing north. Photo shows control measures to protect/stabilize slopes and disturbed areas of the Location remain missing or insufficient. Unable to find evidence that revegetation activities were performed, and BMPs to stabilize seeded soils implemented.

## Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 418697



**Photo 10:** Photo taken from the north end of the Location. Photo show example of Canada thistle rosettes observed on the Location.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 11:** Photo taken from the north end of the Location. Photo show example of Houndstongue, and what appears to be Musk thistle rosettes observed on the Locaiton.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 12:** Photo taken from the north end of the Location, facing west. Photo shows stormwater diversion ditch constructed along perimeter of the Location.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 13:** Photo taken from the northwest corner of the Location, facing north. Photo shows armored section of the Location's perimeter stormwater diversion; control measure inadequate/not in proper functioning condition; stormwater observed scouring/degrading around armor and geotextile lining.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 14:** See comments under photo 13.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 15:** Photo taken from the stormwater diversion ditch on the northwest end of the Location, facing west. Photo shows perimeter stormwater diversion ditch installed on Location is inadequate/insufficient for the site's conditions; ditch not in proper functioning condition; stormwater has breached ditch resulting in additional stormwater erosion degradation.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 16:** Continued from photo 15. Photo shows runoff from the ditch. Photo also shows silt fence along the western perimeter of the Location is inadequate and not in proper functioning condition.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 17:** See comments under photo 15.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 18:** See comments under photo 15

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 19:** Photo shows silt fence along the western perimeter of the Location is inadequate and not in proper functioning condition.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 20:** Photo shows silt fence along the western perimeter of the Location is inadequate and not in proper functioning condition.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 21:** Photo taken northwest end of the Location, facing southeast. Photo shows control measures to protect/stabilize slopes and disturbed areas of the Location remain missing or insufficient; unable to find evidence that revegetation activities were performed, and BMPs to stabilize seeded soils implemented.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 22:** Photo taken from the slopes on the southwest end of the Location, facing north. Photo shows control measures to protect/stabilize slopes and disturbed areas of the Location remain missing or insufficient; unable to find evidence that revegetation activities were performed, and BMPs to stabilize seeded soils implemented.

## Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 418697



**Photo 23:** Photo taken from the west end of the Location. Photo shows Reclamation Specialist was unable to observe evidence that revegetation activities were performed, or BMPs to protect/stabilize the slopes/disturbed areas/seeded soils installed.

## Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 418697



**Photo 24:** Photo taken from the southwest end of the Location, facing north. Photo shows slope drain; unclear if slope drain has been adequately secured. Outlet constructed with geotextile lining and rip-rap armor.

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 418697



**Photo 25:** Photo taken from the ditch on the southeast end of the Location. Photo shows outlet protection of the stormwater diversion ditch has not been installed in accordance with good engineering practices; geotextile liner has been laid upon the soil rather than trenched in.