

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/24/2021

Submitted Date:

05/25/2021

Document Number:

701500858

**FIELD INSPECTION FORM**

Loc ID 315053 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Thompson, Bud		BLThomps@BLM.gov	
Boulger, Levin		lboulger@31operating.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Heil, John		john.heil@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230174	WELL	PR	05/01/2020	GW	103-07833	FEDERAL 4-22	PR

**General Comment:**

A follow up inspection of documents:  
1) 700404769 dated 12-23-2020.

The following were partially completed:  
1) Past due monthly operations were updated to December 2020.

The following compliance issues are uncompleted:  
1) Provide bradenhead access.  
2) Calibrate gas meter.

Additional compliance issues:  
1) Stormwater channels in access road.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type	Area	Volume	corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead access is not present.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: 02/01/2021
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Most recent meter calibration on 6-20-2019.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 02/01/2021
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230174 Type: WELL API Number: 103-07833 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Most recent reported monthly operations is for December 2020 with production in December 2020. Audible gas flow in meter building.](#)  
[Report past due monthly operations by submitting required Form 7\(s\) to COGCC per rule 413.a.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						

Comment: Stormwater channels up to 1' deep are present in the access road. The road has a grade in places of ~8 degrees going uphill to the location.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 06/25/2021

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Blowdown      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date:

**Fencing:**

Fencing Type: Wildlife      Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date:

**Netting:**

Netting Type: Mesh      Netting Condition: Good

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date:

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500859	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440695">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5440695</a>