

Inspection Photos
Location Name: Spicer 3-32H
Location ID: 324754



Photo 1. Battery sign at entrance incomplete.



Inspection Photos
Location Name: Spicer 3-32H
Location ID: 324754



Photo 2. Wellhead sign incomplete/inaccurate.



Photo 3. Tank battery sign at battery incomplete/inaccurate.



Inspection Photos
Location Name: Spicer 3-32H
Location ID: 324754



Photo 4. Tank label incomplete/inaccurate.



Photo 5. Sign at entrance incomplete/inaccurate.

