

Inspection Photos
Location Name: Surprise Unit 0680 S9
Location ID: 445005



Photo 1. Wellhead sign incomplete/inaccurate.



Photo 2. Wellhead sign incomplete/inaccurate.



Inspection Photos
Location Name: Surprise Unit 0680 S9
Location ID: 445005



Photo 3. Wellhead sign incomplete/inaccurate.



Photo 4. Tank label inaccurate.

