

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/18/2021

Submitted Date:

05/26/2021

Document Number:

689805815

**FIELD INSPECTION FORM**

Loc ID 436801 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
5 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 10598  
 Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC  
 Address: 123 ROBERT S KERR AVE  
 City: OKLAHOMA CITY State: OK Zip: 73102

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Boyer, David	303-994-0000	david@d90energy.com	
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436790	WELL	PR	07/01/2020	OW	057-06526	Surprise Unit 2-08H	PR

**General Comment:**  
 Routine follow up inspection. Follow up to inspection from 3/1/2021 document number 689805467. No corrective actions appear to have been met. Form 9 to transfer from Sandridge to D90 received 5/12/2021 document number 402676753, form remains In Process  
 Compliance issues observed:  
 wellhead sign incomplete/inaccurate  
 no emergency contact for D90 on location

**Location**

Overall Good:

**Signs/Marker:**

Type WELLHEAD

Comment: Sign not posted or information inaccurate at well(s).  
Well signs must contain: the well name, the API number, and the legal location including the quarter/quarter section.

Corrective Action: Install sign to comply with Rule 605.d.

Date: 05/11/2021

**Emergency Contact Number:**

Comment: Emergency number on wellhead sign is for Sandridge.

Corrective Action: Install sign to comply with Rule 605.

Date: 06/25/2021

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 436790 Type: WELL API Number: 057-06526 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689805816	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5441455">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5441455</a>