

Construction and Stormwater Inspection

May 19, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 479193

Inspection Document #: 697502929

Weld County, CO

SESW Section 16 T8N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Reeman DE Pad
Location ID: 479193



Photo 1. Photo taken from the entrance of location, facing West. Photo illustrates the major vehicle tracking device BMP has still not been installed.

Inspection Photos
Location Name: Reeman DE Pad
Location ID: 479193



Photo 2. Photo taken from the entrance of location, facing South. Photo illustrates no vehicle track out was observed.



Photo 3. Photo taken from the entrance of location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: Reeman DE Pad
Location ID: 479193



Photo 4. Photo taken from the northeastern location, facing Northeast. Photo illustrates the detention pond has been installed.

Inspection Photos
Location Name: Reeman DE Pad
Location ID: 479193



Photo 5. Photo taken from the stabilized outlet of the detention pond, facing Southwest.



Photo 6. Photo taken from the northeastern location, facing East. Photo illustrates a check dam that is in need of further construction.

Inspection Photos
Location Name: Reeman DE Pad
Location ID: 479193



Photo 7. Photo taken from the northwestern location, facing North. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking.



Photo 8. Photo taken from the northwestern location, facing East. See comments under Photo 7.

Inspection Photos
Location Name: Reeman DE Pad
Location ID: 479193



Photo 9. Photo taken from the entrance of the facility. Photo illustrates the approved Form 2A permits.



Photo 10. Photo taken from the entrance of the facility, facing West. Photo illustrates no outlet protection has been installed.

Inspection Photos
Location Name: Reeman DE Pad
Location ID: 479193



Photo 11. Photo taken from the southeastern location, facing West. Photo illustrates ponding in the ditch which is not being directed to the detention pond.



Photo 12. Photo taken from the southeastern location, facing North. See comments under Photo 11.