

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2021

Submitted Date:

05/26/2021

Document Number:

699303876

FIELD INSPECTION FORM

Loc ID 434492 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

22 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|-----------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 452027 | WELL | PR | 08/01/2018 | OW | 123-45370 | Bison Ridge Y22-756 | PR |
| 452029 | WELL | PR | 09/07/2018 | OW | 123-45372 | Bison Ridge Y22-771 | PR |
| 452030 | WELL | PR | 08/30/2018 | OW | 123-45373 | Bison Ridge State Y22-786 | PR |
| 452033 | WELL | PR | 08/01/2018 | OW | 123-45376 | Bison Ridge Y22-764 | PR |
| 452035 | WELL | PR | 01/28/2021 | OW | 123-45378 | Bison Ridge Y22-779 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Ag panel | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | barb wire | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------|------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 7 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 20 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 20 | | |

| | | |
|---|------|-------|
| Comment: sand catcher | | Date: |
| Corrective Action: | | Date: |
| Type: Other | # 10 | |
| Comment: methanol | | Date: |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 8 | |
| Comment: | | Date: |
| Corrective Action: | | Date: |
| Type: Bradenhead | # 5 | |
| Comment: appear to be plumbed to surface | | Date: |
| Corrective Action: | | Date: |
| Type: Ancillary equipment | # 20 | |
| Comment: Automation | | Date: |
| Corrective Action: | | Date: |
| Type: Emission Control Device | # 10 | |
| Comment: | | Date: |
| Corrective Action: | | Date: |
| Type: Other | # 2 | |
| Comment: corrosion inhibitor | | Date: |
| Corrective Action: | | Date: |
| Type: Other | # 3 | |
| Comment: high pressure heated separators | | Date: |
| Corrective Action: | | Date: |
| Type: Compressor | # 2 | |
| Comment: | | Date: |
| Corrective Action: | | Date: |
| Type: Gas Meter Run | # 10 | |
| Comment: Cards in meter houses indicate current calibration | | Date: |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------------------------|---|----------|-----------|---------|--------|
| OTHER | 1 | 300 BBLS | STEEL AST | | , |
| Comment: Maintenance | | | | | Date: |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | | |
|--------------------|-------------------------------------|---------------------|---------------------|-------------|--------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | shares containment with crude tanks | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 2 | <50 BBLS | CONCRETE SUMP/VAULT | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| <u>Paint</u> | | | | | |
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | 7 bbl | | | | |
| Other (Type) | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 2 | 100 BBLS | BV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| <u>Paint</u> | | | | | |
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | Shares containment with Crude tanks | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 10 | 500 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| <u>Paint</u> | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |

| | | | | | |
|--|----------|-------------------------------|---------------------|-------------|-------------|
| Other (Type) _____ | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: _____ |
| <u>Wells Served By Facilities Above</u> | | | | | |
| API Number | | <u>AirsID</u> | | | |
| 123-45370 | | API Number _____ AirsID _____ | | | |
| 123-38198 | | | | | |
| 123-45376 | | | | | |
| 123-45373 | | | | | |
| 123-38197 | | | | | |
| 123-38199 | | | | | |
| 123-38195 | | | | | |
| 123-45378 | | | | | |
| 123-45372 | | | | | |
| <u>Venting:</u> | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: _____ |
| <u>Flaring:</u> | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: _____ |

Inspected Facilities

Facility ID: 452027 Type: WELL API Number: 123-45370 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/23/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 452029 Type: WELL API Number: 123-45372 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/23/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 452030 Type: WELL API Number: 123-45373 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/23/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 452033 Type: WELL API Number: 123-45376 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/23/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 452035 Type: WELL API Number: 123-45378 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 02/23/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/26/2021 at approximately 1000 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Noble Energy location:</p> <p style="text-align: right;">Y10-11 at Location #434492 in</p> <p>Weld County Colorado.</p> <p>While there, I observed a Multi well pad and tank battery facility, PR at the time of inspection.</p> <p>During this inspection no compliance issues were observed:</p> <p>See attached photos.</p> <p>Location: dry, Weather: cloudy.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | revasr | 05/26/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 699303877 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5441922 |