

Inspection Photos

API# 081-06240

Operator: GRMR

Insp#: 692403405

Insp Date: 5/14/2021





Photo#1:
View over Location to South.

May 14, 2021



Photo#2:
Close up of ground conditions.



Photo#3:
View into Location from point where access
road had entered site.

May 14, 2021



Photo#4:
View over Location to Northwest.

May 14, 2021



Photo#5:
Access road leading into site to Northwest.

May 14, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#6:
Access road leading out of site to Southeast. Circled area will need to be monitored for initiation of stormwater concern.

Inspection Photos: GRMR PA Beaver Durham API#081-06240