

Inspection Photos

Location Name: LARAMIE ENERGY LLC Esperanza /9-5 Pad

Location ID: 334510



Photo #3941 from entrance to location.



Photo #3942 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Esperanza /9-5 Pad

Location ID: 334510



Photo #3943 Flow line heating insulation open ended and not capped.



Photo #3944 Location lacks stabilization.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Esperanza /9-5 Pad

Location ID: 334510



Photo #3945 Location lacks stabilization.



Photo #3946 No form of tracking BMP at entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Esperanza /9-5 Pad

Location ID: 334510



Photo #3947 No battery sign located at the tank battery.