

Inspection Photos

API: 055-06101

Operator: MANZANO LLC

Inspection Date: 5/26/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06101 | Date: 5/26/2021

Inspection Photos



Photo 1. Drone aerial photo facing northwest along the access road toward the location. Red arrow points the the access road and yellow arrow points to the location which have not been reclaimed per rule 1004.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 5/26/2021

Inspection Photos



Photo 2. Aerial image of the location shows it has not been recontoured and reclaimed. The location is approximately 3.3 acres.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 5/26/2021

Inspection Photos



Photo 3. The pipeline risers still remain at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 5/26/2021

Inspection Photos



Photo 4. Facing southwest overlooking the location. There are multiple areas of erosion along the cut slope and fill slope shown at red arrows.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 5/26/2021

Inspection Photos



Photo 5. The pit remains and is filled in with stormwater. This photo shows the erosion along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 5/26/2021