

Inspection Photos

API: 055-06306

Operator: MANZANO LLC

Inspection Date: 5/26/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 5/26/2021

Inspection Photos




Photo 1. Drone aerial photo facing northwest toward the access road and the location. Red arrow points the the access road and yellow arrow points to the location which have not been reclaimed per rule 1004.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 5/26/2021

Inspection Photos



Photo 2. Aerial image of the location shows the location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 5/26/2021

Inspection Photos



Photo 3. Facing southwest overlooking the location. Part of the location has no vegetation growth and previous inspection identified noxious weeds growing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 5/26/2021

Inspection Photos



Photo 4. Facing north overlooking the location which is approximately 2.3 acres in size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 5/26/2021