

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/26/2021

Submitted Date:

05/27/2021

Document Number:

701500888

FIELD INSPECTION FORM

Loc ID 314686 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 12930

Name of Operator: CALCO DBA CALLISTER CO

Address: 1230 W 1400 N

City: LEHI State: UT Zip: 84043

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Callister, Jan	801-487-4721	jec-apex@outlook.com	
Thompson, Bud		BLThomps@BLM.gov	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229262	WELL	SI	01/15/2014	GW	103-06357	CALLISTER- GOVERNMENT 3	TA

General Comment:

A follow up inspection of documents:

- 1) FIR 679701565 dated 10-30-2018.
- 2) Warning letter 401622289 dated 11-28-2018.
- 3) FIR 679703764 dated 10-30-2018.

The following compliance issues are uncompleted:

- 1) Acquire MIT or plug well.

Additional compliance issues:

- 1) Unused equipment.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	911
Corrective Action:	
Date:	

Good Housekeeping:		
Type	UNUSED EQUIPMENT	
Comment:	Wood, pipe fittings, and pump jack. The inspector was unable to determine which equipment was temporarily moved versus no longer used.	
Corrective Action:	Comply with Rule 606.	Date: 06/28/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	Temporary concrete deadman.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead open to atmosphere.		
Corrective Action:		Date:	

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 229262 Type: WELL API Number: 103-06357 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last recorded production 9-1-2013. Swab test on 10-26-2020. No current MIT on file.Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.Date: 07/31/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening		Slope Roughening				

Comment: [Tank location & access road to tank was reclaimed.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500889	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5442611