

Inspection Photos
Operator: Simcoe
API: 067-06679
Date: 5/24/2021



Photo 1. View of project area from the northwestern corner facing center.



Photo 2. View of the southwestern project area from the northwestern corner facing southeastward. Revegetation is progressing in portions with western wheatgrass and smooth brome. Some portions remain sparse and revegetation should be assessed after weed control efforts.



Photos 3. View of Russian knapweed observed within the project area. Approximately 200 individuals observed.



Photo 4. View of dense jointed goatgrass within the project area. Areas with jointed goatgrass infestation will require re-seeding after infestation is controlled.



Photo 5. View of reference area comprised of pinyon and juniper woodland with western wheatgrass, pricklypear, phlox, and blue grama in the understory.