

Inspection Photos
Operator: Simcoe
API: 067-06481
Date: 5/24/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing in portions with western wheatgrass, rubber rabbitbrush, and blue grama. Cows are present at the time of the inspection.



Photos 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of sagebrush shrubland, with gambel oaks, scattered pinyon and juniper trees, western wheatgrass, pricklypear, phlox, and blue grama in the understory.