

Inspection Photos
Operator: Catamount
API: 007-06095
Date: 5/24/2021



Photo 1. View of project area from the western project area facing center.



Photo 2. View of the northern project area from the northwestern corner facing westward. Revegetation is sparse. Operator discussed need to conduct spot seeding within the interim reclamation areas.



Photos 3. View of the eastern cut-slope. Operator and USFS discussed long term stabilization measures including construction of a ditch, seeding with three different hydro mulch compositions, and erosion control blankets.



Photo 4. View of area at well pad entrance where concentrated stormwater flows out of a culvert and downslope toward a drainage exiting the western edge of the project area. Operator and USFS discussed installing an extended rock apron here and rock checks along erosional channeling (stormwater flowline) downslope.



Photo 5. View of discharge point for the well pad and cut-slope into an ephemeral drainage. Operator and USFS discussed installation of an armored silt trap and discharge point here.