

# Inspection Photos

5/26/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335904

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



Photo 1: Photo shows signage at Location entrance is no longer legible.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 2:** Photo taken from the south end of the frac pad, facing southeast. Photo provides an overview of the Location. Photo also shows Operator has utilized topsoil at the base of the fill slopes/subsoils of the Location as a berm and sediment trap/pond to manage stormwater; topsoil at risk of degradation, loss and displacement due to stormwater discharge

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 3:** Photo taken from the east end of the Location, facing north. Photo show Operator has utilized topsoil at the base of the fill slopes/subsoils of the Location as a berm and sediment trap/pond to manage stormwater; topsoil at risk of degradation, loss and displacement due to stormwater discharge. Photo also shows hydromulch on soils is no longer in proper functioning condition.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 4:** Photo taken from the south end of the Location, facing northwest. Photo provides an overview of the Location.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 5:** Photo taken from the south end of the Location, facing northeast. Photo provides an overview of the Location.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 6:** Photo shows control measures to protect/stabilize the cut/fill slopes of the Location is missing or insufficient.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 7:** Photo taken from the west end of the Location, facing northwest. Photo shows Operator has utilized topsoil at the base of the fill slopes/subsoils of the Location as a berm and sediment trap/pond to manage stormwater; topsoil at risk of degradation, loss and displacement due to stormwater discharge

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



20210526

**Photo 8:** Photo taken from the west end of the Location, facing southwest. Photo show Operator has utilized topsoil at the base of the fill slopes/subsoils of the Location as a berm and sediment trap/pond to manage stormwater; topsoil at risk of degradation, loss and displacement due to stormwater discharge. Photo also shows hydromulch on soils is no longer in proper functioning condition.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 9:** Photo shows control measures to protect/stabilize the cut/fill slopes of the Location is missing or insufficient.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 10:** Photo shows unused pipe equipment/debris observed on the north end of the Location.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 11:** Photo shows conductors and cellars for the undrilled wells.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 12:** Photo shows examples of erosion logs observed that are either not installed in accordance with good engineering practices, or maintained in a proper functioning condition; wattles not trenched/backfilled.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 13:** See comments under photo 11.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 335904



**Photo 14:** Photo taken from the frac pad, facing northwest. Photo shows hydromulch on soils is no longer in proper functioning condition.