

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402675506

Date Received:

04/29/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Olson, Andrew

andrewolson@chevron.com

Patterson, Chris

spwu@chevron.com

Sanford, Anita

atlx@chevron.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202604

Inspection Date: 04/23/2021

FIR Submit Date: 04/26/2021

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 314804

Location Name: CARNEY C T-62N102W Number: 35NWNE County: _____

Qtrqr: NWNE Sec: 35 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.106770 Longitude: -108.810490

FACILITY - API Number: 05-103- -00 Facility ID: 314804

Facility Name: CARNEY C T-62N102W Number: 35NWNE

Qtrqr: NWNE Sec: 35 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.106770 Longitude: -108.810490

CORRECTIVE ACTIONS:

1 ☒ CA# 150100

Corrective Action: Comply with Rule 1002.f.(2)C and install required stormwater and erosion control BMPs; ensure control measures are adequate for the site's conditions, installed in accordance with good engineering practices, and are maintained in a proper functioning condition.

Date: 04/30/2021

Response: CA COMPLETED

Date of Completion: 04/29/2021

Operator Comment: 1. Carney CT 24X35 well pad was bladed and ruts were removed.
2. The access road was graded and ruts removed.
3. A berm was placed on the east side of the access water to move water into the diversion ditch on the east side of the pad.
4. A water bar was installed across the access road to drain any water from the access road to the west side of the road into the diversion ditch on the west side of the access road and pad.
5. The access road was graded to drain water from the access road to the west side of the road into the west side diversion ditch.

Please see the attached pictures that show further document the above.

COGCC Decision: **Not Approved**

COGCC Representative: Based on the photos provided, additional control measures have been implemented to manage runoff/runoff, however, control measures to stabilize the production area/access road, and to prevent off-site sediment transport during wet conditions are not evident within the photo documents provided. Operator comments below also do not identify any control measures to address tracking and stabilization concerns.

Based on information provided, corrective action does not appear to have been addressed in its entirety.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see comments and attached photo

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: _____

Title: Lead ENV Specialist

Date: 4/29/2021 12:46:47 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402675506	FIR RESOLUTION SUBMITTED
402675519	Photo

Total Attach: 2 Files