

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2021

Submitted Date:

05/28/2021

Document Number:

679603883**FIELD INSPECTION FORM**Loc ID 332971 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Burn, Diana		diana.burn@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Gomez, Jason		jason.gomez@state.co.us	
		jennifer.morse@state.co.us	
		jennifer.mattox@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239987	WELL	PR	02/01/2021	OW	123-07775	HLADKY-O'GORMAN 3	SI

**General Comment:**[This is a FLIR inspection. All previous corrective actions assigned to this location remain in affect until completed by operator.](#)

Inspected Facilities									
Facility ID:	239987	Type:	WELL	API Number:	123-07775	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: PRODUCTION RECORDS									
Comment: <input type="text"/>									
Corrective Action: <input type="text"/> Date: <input type="text"/>									

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.123443 Long: -104.788254Wind: Calm Speed: 3 (mph) Direction From: N Weather: Cloudy Temperature: (F)Assisting Staff Robbie Revas Camera #: ☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
10:40	AM	11:10	AM	Wellhead(s)

Comment: Gas being vented during non-upset condition without prior approval from COGCC.Corrective Action: Immediately cease venting. Submit Form 4 for review and approval to vent per Rule 903.d.(2).Date: 05/14/2021**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b></p> <p><b>**Weather Conditions: cloudy, muddy</b></p> <p>On May 12, 2021 at approximately 10:40, I, Inspector Brittani Santistevan, conducted an on-site inspection at HLADKY-O'GORMAN #3 (KP KAUFFMAN), at location: 332971 in WELD Colorado.</p> <p>While there, I observed a shut in facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. A FLIR video was conducted on location of the pumpjack and it appears in the video that gas is being vented during non-upset condition without prior approval from COGCC.</p> <p>Immediately cease venting. Submit Form 4 for review and approval to vent per 903.d.(2). See attached videos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	05/28/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603920	Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5444155">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5444155</a>