

Construction and Stormwater Inspection

May 25, 2021

Operator: PROVIDENCE OPERATING LLC DBA POCO
OPERATING- #10694

Location ID: 460271

Inspection Document #: 697502949

Weld County, CO

NWSE Section 35 T1N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Double J /35-11 Pad
Location ID: 460271



Photo 1. Photo taken from the entrance of location, facing West. Photo illustrates major construction activities have commenced. Operator has installed a ditch BMP along the outer perimeter of the access road.

Inspection Photos
Location Name: Double J /35-11 Pad
Location ID: 460271



Photo 2. Photo taken from the northern location, facing East. Photo illustrates Operator has installed a ditch and berm BMP around the entire perimeter of the location during construction activities.



Photo 3. Photo taken from the northern location, facing East. Photo illustrates that topsoil appears to be stored along the northern and eastern perimeter of location.

Inspection Photos
Location Name: Double J /35-11 Pad
Location ID: 460271



Photo 4. Photo taken from the southern location, facing West. See comments under Photo 2.



Photo 5. Photo taken from the western location, facing North. Photo illustrates topsoil salvage operations are underway at the time of this inspection along the production facility.