

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2021

Submitted Date:

06/01/2021

Document Number:

696900160

**FIELD INSPECTION FORM**

Loc ID: 318936 Inspector Name: CHESSON, BOB On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
KPK		cogcc@kpk.com	All Inspections
Allison, Rick		rick.allison@state.co.us	
Allison, Rick		rick.allison@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478276	TANK BATTERY	AC	10/13/2020		-	Opal Tank	SI
478277	OFF-LOCATION FLOWLINE	AC	10/13/2020		-	Wellhead Line 34SWSW	SI

**General Comment:**

This is an inspection in response to complaint #200449719.  
I inspected the location along with Randy Silver, COGCC field inspector. RS was conducting a follow-up inspection to evaluate compliance issues noted on inspection #693503282.  
  
No spills or stained soils observed either at the oil tank or in the treater shed.  
  
Flowline trace marked with flags from TB to wellhead (approximately 600 feet) in a straight line-of-sight. As shown on COGCC GIS map layer for flowlines provided on the flowline information on 10/13/2020 (Facility ID 478277) and COGCC GIS map. The well is currently SHUT-IN.  
  
See inspection photographs.

**Inspected Facilities**

Facility ID: <u>478276</u>	Type: <u>TANK</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>SI</u>
----------------------------	-------------------	----------------------	-------------------	-------------------------

Facility ID: <u>478277</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>SI</u>
----------------------------	-------------------	----------------------	-------------------	-------------------------

**COGCC Comments**

Comment	User	Date
<p>This is an inspection in response to complaint #200449719. I inspected the location along with Randy Silver, COGCC field inspector. RS was conducting a follow-up inspection to evaluate compliance issues noted on inspection #693503282.</p> <p>No spills or stained soils observed either at the oil tank or in the treater shed.</p> <p>Flowline trace marked with flags from TB to wellhead (approximately 600 feet) in a straight line-of-sight. As shown on COGCC GIS map layer for flowlines provided on the flowline information on 10/13/2020 (Facility ID 478277) and COGCC GIS map. The well is currently SHUT-IN.</p> <p>See inspection photographs.</p>	chessonr	06/01/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696900161	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5444615">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5444615</a>