

Inspection Photos

API: 055-06316

Operator: OXY USA INC

Inspection Date: 5/26/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 5/26/2021

Inspection Photos



Photo 1. There is erosion occurring down the road ascending to the location. Areas of erosion will need to be repaired and BMP's need maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 5/26/2021

Inspection Photos



Photo 2. The sediment trap along the road has filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 5/26/2021

Inspection Photos



Photo 3. Stormwater is causing erosion along the road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 5/26/2021

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 5/26/2021