

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2021

Submitted Date:

06/02/2021

Document Number:

701101585

FIELD INSPECTION FORM

Loc ID 335325 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259571	WELL	PR	07/20/2001	GW	045-07749	PA 323-32	PR
270137	WELL	PR	05/29/2004	GW	045-09467	PA 523-32	PR
270138	WELL	PR	05/25/2004	GW	045-09466	PA 423-32	PR

General Comment:

[COGCC Follow Up Inspection Report Summary](#)
Location is in close proximity of Colorado River and creeks that run to the river in a High Priority Habitat Area. (Mule Deer Winter Concentration Area)
Follow up to 03/09/2021 inspection # 701101246
All Corrective Actions have been performed

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Signs are weathered.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Type: Deadman # & Marked				
Comment:	Deadman marked			
Corrective Action:			Date:	
Type: Bradenhead		# 3		
Comment:	Braden head accessible for monitoring.			
Corrective Action:			Date:	
Type: Plunger Lift		# 3		
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 259571 Type: WELL API Number: 045-07749 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 270137 Type: WELL API Number: 045-09467 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 270138 Type: WELL API Number: 045-09466 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Compaction				
Compaction						
		Gravel				
Seeding						
Gravel						
		Culverts				
Ditches						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101586	Inspection 701101585 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445450