


Inspection Photos  
Operator: Simcoe  
API: 067-07228  
Date: 5/28/2021



Photo 1. View of project area from the southwestern project area facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and smooth brome, largely in a grazed condition.



Photos 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of the northern project area from the northwestern corner facing eastward.



Photo 5. View of reference area vegetation comprised of irrigated grass field, largely in a grazed vegetative condition.



Photo 6. View of closed gate after leaving location.